

Improving Connections Within Focus Areas

- **Pedestrian and bicycle improvements in Village of Conestoga**
 - Why – Existing sidewalks along Main Street corridor, but difficult intersection geometry and crossing distances for bike and pedestrian users
 - Solution – Traffic calming (gateway treatments, crosswalks, curb extensions); access management ordinance; official map; road connections
 - Best Practices – Crosswalks in Brownstown; gateway islands in Chatham, Chester County

Existing Conditions:

- Main Street, Conestoga



Best Practices:

- Main Street, Brownstown



- PA Route 41, Chatham, Chester County



- **Managing freight traffic around Turkey Hill Dairy / Frey Farm Landfill area**
 - Why – Truck traffic, manufacturing plant, landfill
 - Solution – Regional official map to account for freight transportation; possible changes to zoning; access management ordinance
 - Best Practices – PA Route 441 bypass project in Columbia Borough to re-route truck traffic from downtown area

Existing Conditions:

- Turkey Hill Dairy / Frey Farm Landfill Area



Best Practices:

- PA Route 441 bypass / NW River Trail, Columbia Borough

